

77005

To the Gunsmiths:

1- model 721 30-06 Rifle:

PLEASE PERFORM BOLT LOCK REMOVAL, +
CHECK SAFETY PER RECALL ADVISORY.
I HAVE EXPERIENCED AN ACCIDENTAL
DISCHARGE. IF BOLT LOCK IS NOT THE ONLY
PROBLEM, PLEASE DO WHATEVER WORK IS
REQUIRED TO RETURN THE WEAPON TO SAFE,
USABLE SERVICE.

Steve Cook
7/49

1- model 722 .222 Rifle

Although this gun comes under the
Recall Advisory (BOLT LOCK, SAFETY), the
original trigger + SAFETY HAS BEEN REPLACED
WITH A "CUSTOM" SET TRIGGER. I HAVE DISCOVERED
THE TRIGGER TO BE PRONE TO UNWANTED, SPONTANEOUS
FIRING, THUS ~~MAKING~~ MAKING THE GUN UNSAFE.
I WOULD LIKE TO HAVE ORIGINAL REMINGTON
PARTS REINSTALLED; GUN RETURNED TO SAFE
WORKING ORDER. I REALIZE THIS WILL
ACQUIRE CONSIDERABLE PARTS + LABOR.
PLEASE ADVISE, SINCERELY

Eric Anderson

PHONE: 978-297-1536

CELL: 978-621-4477