

### Repair Order Number



<b>Repair Order Number</b> RE00078127	<b>Description/Serial Number</b> C6843477	<b>Repairman -</b> Chuck Dekanek
<b>Account # - R-</b>	<b>Model 700 Center Fire Caliber: 308</b> POLICE SNIPER RIFLE	<b>Date Received -</b> 3/8/2004
<b>Customer</b> ANNISTON POLICE DEPARTMENT		<b>Estimate Date -</b>
<b>P.O. BOX 2168</b> ANNISTON, AL 36201 US		<b>Current Date -</b> 3/10/2004
<b>Phone (H)</b> (256)-231-7708		<b>Return To</b> ANNISTON POLICE DEPARTMENT 1128 GURNEE AVE ANNISTON, AL 36202 US
<b>Phone (W)</b>	<b>Fax</b>	<b>Email</b>

Reported		Problems		Found	
M123	FORWARD TO PRODUCT SERVICE FOR INSPECTION			M123	FORWARD TO PRODUCT SERVICE FOR
M992	GUN FIRED WHEN SWITCHED FROM SAFE				

<u>Material #</u>		<u>MaterialDesc</u>	<u>Quantity</u> <u>Needed</u>	<u>Quantity</u> <u>From Inv</u>	<u>Quantity</u> <u>From Kit</u>	<u>Warranty</u> <u>(Y/N)</u>
<b>Part</b>						
F26345		700 TRIG ASSB RH	1	1	0	Y
<b>Part Total:</b>			1	1	0	
<b>Service</b>						
4000294		GR-CHECK TPA	1	1	0	Y
4000104		ARMS SERV SHIPPING & HANDLING	0	0	0	Y
4000119		GR-TEST	1	1	0	Y
<b>Service Total:</b>			2	2	0	

**ProblemNotes** Could not duplicate as received. Trigger assembly extremely heavy oil, some rust visible on pin hole. Install new trigger assembly and clean action at no charge as a gesture of goodwill. FLS 3/8/04

Repairman	Proof	Clean	Test	Target	Pattern
Gallery Tester	Date	Date	Date	Date	Date