

Date: 3/8/2004

By: FRED SUPRY

FIREARM INSPECTION WORKSHEET

BACKGROUND

Customer name: Anniston PD

R.E. Number: 78127

Reason for inspection: FSR Concern

FIREARM

Manufacturer: REM Model: 700

Serial Number: C6843477 Date of Manufacture: 11/15/1993

Overall external condition: good

Barrel condition: good

Receiver condition: good

Stock condition: good

Bolt/firing pin condition: good

Trigger assembly condition:

Engagement: OK

Adjustments/alterations: none visible

Other: Saturated with heavy oil

Headspace: —

Function evaluation:

Feeding: _____

Extraction/ejection: _____

Trigger pull: OK

Manual safety: OK

Test firing results (if applicable): _____

DISPOSITION

Install new TA & Clean action

ADDITIONAL COMMENTS

Disassembly of TA showed some rust
between the trigger pin and trigger pin hole
in the trigger.

Sear was sluggish due to excess oil in
TA.