

Remington.

Factory Repair Instructions

(NOTE: Please print and complete this form, and then include it with your firearm.)

Model Number: 700LTR		Serial Number: E6602872	
Are you the original owner? <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO			
Name: Brian Anthony		Date of Purchase: 28 Feb 00	
Address (no PO Boxes): 1009 Hidden Branch Trail			
City: Centon		State: GA	Zip: 30115
Phone (Daytime): 678-665-2408		Fax: 770-345-9542	
E-mail Address: banthony1@att.net			
<input checked="" type="checkbox"/> I would like to receive future e-mail updates from Remington.			
Please describe your problem:			
Safety is broken. Firearms discharge when moving safety lever from safe to fire. Note trigger was <u>not</u> depressed			
Ammunition Information:			
Manufacturer: Federal		Type: H308A 308 Win 150 Gr 3/4 Pt	
Other (i.e. bullet weight/type, shot size, powder):			
Handload Information:			
Powder Used: n/A		Powder Weight:	
Case/Hull Used:		Primer Used:	
Bullet Type/Shot Size:		Reloader Used:	
Firearms Care (Cleaning and Lubrication):			
Brand of cleaning solution used:			
How often do you clean the bore? (Months or Number of rounds) Every time weapon is fired			
How often do you clean the action? (Months or Number of rounds) Every time weapon is fired			
How often do you clean the trigger assembly? (Months or Number of rounds) never. Department policy is to only allow armorer or factory to touch trigger			
Brand of lubricant used: Tetra Gun Grease			