

Date: 4/12/05

By: Bruce Travis SR.

FIREARM INSPECTION WORKSHEET

BACKGROUND

Customer name: Rickey W. Hendry

R.E. Number: 95722

Reason for inspection: delays firing

FIREARM

Manufacturer: Rem. Model: 600

Serial Number: A6639614 Date of Manufacture: 7/76

Overall external condition: Good

Barrel condition: OKAY

Receiver condition: OKAY

Stock condition: OKAY

Bolt/firing pin condition: OKAY

Trigger assembly condition:

Engagement: —

Adjustments/alterations: —

Other: Dirty/sticky

Headspace: —

Function evaluation:

Feeding: —

Extraction/ejection: —

Trigger pull: 4#

Manual safety: O.K. 124

Test firing results (if applicable): —

DISPOSITION

could not duplicate concern. replace complete TPA under
T.A. recall n/t/c. check over & clean action

ADDITIONAL COMMENTS