

Remington.

TRACKING DOCUMENT

Repair Order Number



Repair Order Number RE00051481	Description/Serial Number D6839308	Repairman - Robert Frink Date Received - 9/10/2002
Account # - R-	Model 700 Center Fire Caliber: 7MM MAG ADL SYNTHETIC LESS GRIP CAP	Estimate Date - Current Date - 9/12/2002
Customer ARCHERY AND GUN OUTFITTERS 674 BETHLEHEM PIKE MONTGOMERYVILLE, PA 18936 US		Return To ARCHERY AND GUN OUTFITTERS 674 BETHLEHEM PIKE MONTGOMERYVILLE, PA 18936 US
Phone (H) (215)-368-3600 Phone (W)		Fax Email

Reported	Found
M123 FORWARD TO PRODUCT SERVICE FOR INSPECTION	M123 FORWARD TO PRODUCT SERVICE F
M992 GUN FIRES WHEN SAFE IS TAKEN OFF	

Material #	MaterialDesc	Quantity Needed	Quantity From Inv	Quantity From Kit	Warranty (Y/N)
Part					
F26345	700 TRIG ASSB RH	1	1	0	N
Part Total:		1	1	0	
Service					
4000104	ARMS SERV SHIPPING & HANDLING	0	0	0	N
4000119	GR-TEST	1	1	0	N
Service Total:		1	1	0	

ProblemNotes		Action and trigger assembly dirty. Poor maintenance. Altered settings. Replace trigger assembly at 1/2 MSP. D.S.			
Repairman	Proof	Clean	Test	Target	Pattern
Gallery Tester	Date	Date	Date	Date	Date

REMINGTON ARMS CO INC
800 243-9700
14 HOFER AVE
ILION NY 13357


11 LBS 1 OF 1

COD

SHIP

TO:

ARCHERY AND GUN OUTFITTERS
674 BETHLEHEM PIKE
MONTGOMERYVILLE PA 18936




PA 189 0-03



UPS GROUND

TRACKING #: 1Z 114 813 72 1194 2052



BILLING: P/P
COD \$45.29

INV#: RE00051481

A9C 05.00 J69K/J64K 16.0A 01/2002