

CEIVING AND ESTIMATING REPORT

COMMENTS

R 93-11141

CUSTOMER ORDER NO.

RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE
7/30/93	05/03/93	CG 4-86	B6782962		700 30-06 MTN
SOURCES W/STUDS SCOPE BASE					

Setup pull
ARMY SURPLUS I
501 OAK STREET
SANDPOINT

ID 83864

SHIP TO:

ARMY SURPLUS I
501 OAK STREET
SANDPOINT

ID 83864

CUST NO: 078739 C.O.D.L.

QUANTITY NUMBER	ACCOUNT NUMBER N/C <i>059001</i>	PROM. DATE	ESTIMATED	VIA UPS
CONDITION	<i>[Large handwritten area]</i>			REPAIR CHARGE
VIEW				EXCISE
IGHTLY WORN				TAX
WORN				INSURANCE
VERY WORN				UPS
UNREPAIRABLE				PARCEL POST
DAMAGED				TOTAL

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
BLE	A1	B1				
GROUP		B2				F1
T ASSY.						
REL ASSY.				D1	E3	F3
ASSY.		B5		D2	E4	F4
OD			C1	D3	E5	F5
FAL			C2			

Handwritten notes:
Unable to duplicate Customer Concern.
Ammunition revealed the action, trigger assembly, and bolt stop return
found with heavy, lumpy lubrication. More than normal force required
to trigger. Safety.

TS	COMMENTS				
<i>Gun left - D11</i> <i>Trigger Pull - 5 1/2 lbs.</i>	<i>Replace complete trigger assembly & clean action at no charge</i>				
REPAIRMAN <i>FB.</i>	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 1/92

PS00760