

File Number:	16146	Arms Service number:	26521
Last Name:	ARNESON	First Name:	KELLY
Street:	11 WILLOW	City:	LEWISTOWN
State:	MT	Zip:	59457
Work Ph:		Home Ph:	
Type Concern:	S	Product Type:	F F A T O
	PI PD P S	Concern Code:	1007
Concern:	FIRED ON SAFE RELEASE		
Cause Code:	4040	Cause:	OTHER - UNSPECIFIED OR UNDETERMINED
Assigned To:	SUPRY	Classification:	UND UNJ UNC UND
Settlement Detail:	INSTALL NEW TA AT SPECIAL PRICE	Settlement Amount:	\$0.00
Date Opened Rem:	4/24/01	Date Opened by P/S:	4/24/01
Date of Incident:	11/1/00	Caliber:	2506
	Date Closed:	Bullet Weight:	
	4/24/01		
Date to Analysis:		Date from Analysis:	
		Manufacturer:	
Model:	700	Date Code:	OQ
Serial:	A6630426	Date Mfgd:	7/1/78
RAMAC:	700	Litigation:	☐
		PreLitigation:	☐
		Obsolete:	☐
Custody:		Comments:	Could not duplicate concern - some sticky residue - Sear cam works freely - Bolt release sluggish - Install new TA at 1/2 MSP.
Time of Modification:	12:08:49 PM		
Date of Modification:	4/24/01		