



TRACKING DOCUMENT

Repair Order Number



Repair Order Number RE00054893	Description/Serial Number T6232003	Repairman - Robert Frink Date Received - 11/4/2002
Account # - R-	Model 700 Center Fire Caliber: 2506 BDL DM SS ENHCD	Estimate Date - Current Date - 11/7/2002
Customer ARROWHEAD GUN SHOP 1241 JUNCTION HWY KERRVILLE, TX 78028 US	Return To ARROWHEAD GUN SHOP 1241 JUNCTION HWY KERRVILLE, TX 78028 US	
Phone (H) Phone (W)	Fax Email	

Problems			
Reported		Found	
M123	FORWARD TO PRODUCT SERVICE FOR INSPECTION	M123	FORWARD TO PRODUCT SERVICE F
M992	FIRES WHEN TAKEN OFF SAFE		

Repair					
<u>Material #</u>	<u>MaterialDesc</u>	<u>Quantity Needed</u>	<u>Quantity From Inv</u>	<u>Quantity From Kit</u>	<u>Warranty (Y/N)</u>
Part					
F97490	700 SS TRIG ASSB RH	1	1	0	N
Part Total:		1	1	0	
Service					
4000104	ARMS SERV SHIPPING & HANDLING	0	0	0	N
4000119	GR-TEST	1	1	0	N
Service Total:		1	1	0	

ProblemNotes	Trigger assembly rusty and adjustment screws have been re-set. Replace trigger assembly at 1/2 MSP. D.S.				
Repairman	Proof	Clean	Test	Target	Pattern
Gallery Tester	Date	Date	Date	Date	Date