File Number: 19682	Arms Service number: 74894
Last Name: ARWADY SALES First Name: AMMO DUMP	
Street: 11117 POST OAK ROAD	City: HOUSTON
State: TX Zi	p. 77035 Home Ph: 1
Work Ph: 713-723-8583	Product Type: FATO
Type Concern: PD PI	PD P S Concern Code: 1008
Concern: FIRED ON BOLT CLC	DSING
Cause Code: 4040 Cau	use: OTHER - UNSPECIFIED OR UNDETERMINED
Assigned To: SUPRY	Classification: UND UNJ UNC UND
Settlement Detail: BLM PROG	RAM Settlement Amount: \$0.00
Date Opened Rem: 1/5/2004	Date Opened by P/S: 1/6/2004 Caliber: 3006
Date of Incident:	Date Closed: 1/7/2004 Bullet Weight:
Date to Analysis:	Date from Analysis: Manufacturer:
Model: 700 Serial:	113394 Date Code: Date Mfgd:
RAMAC: 700	Litigation: PreLitigation: Obsolete:
Custody: Com	Ments: Older vintage M/700 - Could not duplicate FOBC concern. As received the stock was broken, the front screw out of the trigger guard. Broken stock may have been the result
Time of Modification: 9:47	7:45 AM of poor packing when the rifle was shipped to Remington. Clean action and install new TA. Quote \$20 under the bolt lock modification program. Quote replacement stock at
Date of Modification: 1/7/2004	1/2 MSP as gesture of goodwill. Repair and shipping documents 2/17/04.
	중算 學學學 보다는 그가 되었다.