



TRACKING DOCUMENT

Repair Order Number



Repair Order Number RE00074894	Description/Serial Number 113394	Repairman - Carl Cotton
Account # - R-	Model 700 Center Fire with 20 inch barrel Caliber: 30-06 ADL	Date Received - 1/26/2004
		Estimate Date - 1/7/2004
		Current Date - 2/11/2004
Customer ARWADY SALES 11117 S POST OAK ROAD HOUSTON, TX 77035 US		Return To ARWADY SALES 11117 S POST OAK ROAD HOUSTON, TX 77035 US
Phone (H) (713)-723-8583		Fax
Phone (W)		Email

Problems			
Reported		Found	
M123	FORWARD TO PRODUCT SERVICE FOR INSPECTION	M112	HEADSPACE IS EXCESSIVE
M125	STOCK CRACKED	M125	STOCK CRACKED
M992	FIRES WHEN CHAMBERING SHELL	M239	REPLACE TRIGGER ASSEMBLY

Repair					
<u>Material #</u>	<u>MaterialDesc</u>	<u>Quantity Needed</u>	<u>Quantity From Inv</u>	<u>Quantity From Kit</u>	<u>Warranty (Y/N)</u>
Part					
F26345	700 TRIG ASSB RH	1	1	0	N
F92897	700 BOLT ASSB BDL MAX LONG F1	1	1	0	Y
F93712	700 EXTRACTOR REG (7400;710)	1	1	0	Y
Part Total:		3	3	0	
Service					
4000244	GR-PARTS USED IN REPAIRS (MISC)	30	30	0	N
4000294	GR-CHECK TPA	1	1	0	Y
4000104	ARMS SERV SHIPPING & HANDLING	0	0	0	Y
4000116	GR-LABOR	20	20	0	N
4000117	GR-PROOF	1	1	0	Y
4000119	GR-TEST	1	1	0	Y
Service Total:		53	53	0	

ProblemNotes	Stock broken at the bolt handle cut and cracked at the mag. box. Has the old style bolt lock safety. Quoted for replacing trigger assy. under the bolt lock safety program. Replacing stock and bolt with good used.				
Repairman	Proof	Clean	Test	Target	Pattern
Gallery Tester	Date	Date	Date	Date	Date