



AMMO DUMP
A Division of ARWADY SALES
AUTHORIZED HECKLER & KOCH DEALER



12/28/03

ATAW Repair:

Serial# 113394

Re: this Remington Rifle. is Very Dangerous!
It must have a SEAR Problem.

It will discharge upon cocking
Without trigger pull.

Please Repair -

Bob Arwady

Serial
Number:

113394

Model: 700



RE00074894

As Received front screw out of trigger guard, stock broken
Can not duplicate concern. Install new TA and clean action
Quote \$20 under bolt lock modification program.

Quote stock at $\frac{1}{2}$ MSP -

FLS 1/6/2004

