

<b>File Number:</b>	15965		<b>Arms Service number:</b>	24335	
<b>Last Name:</b>	ASSIF		<b>First Name:</b>	JOSEPH	
<b>Street:</b>	225 MERIDEN ROAD		<b>City:</b>	WATERBURY	
<b>State:</b>	CT	<b>Zip:</b>	06705	<b>Home Ph:</b>	203-753-3014
<b>Work Ph:</b>		<b>Product Type:</b>	F	F A T O	
<b>Type Concern:</b>	S	PI PD P S	<b>Concern Code:</b>	1007	
<b>Concern:</b>	FIRED ON SAFE RELEASE				
<b>Cause Code:</b>	4006	<b>Cause:</b>	ALTERED ADJUSTMENTS OR COMPONENTS		
<b>Assigned To:</b>	SANITA	<b>Classification:</b>	UNJ	UNJ UNC UND	
<b>Settlement Detail:</b>	REPLACE TA AT SPECIAL PRICE		<b>Settlement Amount:</b>		
<b>Date Opened Rem:</b>	3/12/01	<b>Date Opened by P/S:</b>	3/12/01	<b>Caliber:</b>	7MM MAG
<b>Date of Incident:</b>		<b>Date Closed:</b>	3/12/01	<b>Bullet Weight:</b>	
<b>Date to Analysis:</b>		<b>Date from Analysis:</b>		<b>Manufacturer:</b>	
<b>Model:</b>	700	<b>Serial:</b>	6514074	<b>Date Code:</b>	AW
<b>Date Mfgd:</b>	3/1/72				
<b>RAMAC:</b>	700	<b>Litigation:</b>	<input type="checkbox"/>	<b>PreLitigation:</b>	<input type="checkbox"/>
<b>Obsolete:</b>	<input type="checkbox"/>				
<b>Custody:</b>		<b>Comments:</b>	upon receipt the sear safety cam was seized up from beint covered with a brown sticky substance - All three adjuustment setting altered. Rifle poorly maintained, Replace TA at 1/2 MSP		
<b>Time of Modification:</b>	11:38:03 AM				
<b>Date of Modification:</b>	3/12/01				