

Serial Number: **B6346329**

Model: **700**



RE00024841

Date *EB*
Call *10/81*

3/23/01

Refill would fire when you push safety forward

*Action & trigger assembly covered with a sticky substance
near safety when working sluggish.*

*Replace trigger assembly & clean action at
1/2 MSP. Go ahead*