



944 Bonifant Street
Silver Spring, Md 20910

(301) 585-4448
FAX (301) 585-5935

Memo

LETTER

Date

4/6/95

Subject

Remington Arms Co Inc
14 Hoefer Ave
Elion New York
13357

Please repair the following firearm (Warranty)

Model 700 Sendero SN#C6893450
My customer just bought this gun from us
and claims the gun fired when he closed the bolt.
He claims this happened 3 times when shooting at
the range. I took the action out of the stock
to inspect the gun and I found that the recoil lug
is not strait in line with the action and trigger.
When the action is in the stock it may be binding
the trigger mec?

☐ Please reply

☐ No reply necessary

SIGNED

Thank you
Scott Schopf



40% Pre-Consumer Content • 10% Post-Consumer Content

OFFICE COPY

DATE

DATE

TEST

TARGET

PS00841