

# Remington®

## Repair Form

(NOTE: Please print and complete this form, and then include it with your firearm.)

<b>Model Number:</b> 721	<b>Serial Number:</b> 125429	
<b>Name:</b> Glenn Austin	<b>Date of Purchase:</b> 11/7/2002	
<b>Address (no PO Boxes):</b>		
6 Bickford Ave		
<b>City:</b> Brunswick	<b>State:</b> Me	<b>Zip:</b> 04011
<b>Phone (Daytime):</b> 207-373-6702	<b>Fax:</b> 207-373-6710	
<b>E-mail Address:</b> gaustin@midcoasthealth.com		
<b>Please describe your problem:</b>		
- Bolt lock safety modification program		
- Also trigger sticks in conjunction with safety. When this occurs the rifle does not fire until unexpectedly when the safety is jarred slightly		
<b>Additional Information: (Ammo type, brand, handload specifications, etc.)</b>		

**NOTE: Prior to shipping your firearm, call 1-800-421-0000 for a quote, parts provided and estimated repair time.**

**⚠ WARNING: DO NOT SEND LIVE OR SPENT SHELLS IN YOUR FIREARM. THIS IS A VIOLATION OF FEDERAL LAW. IF YOU FEEL YOU NEED TO RETURN YOUR FIREARM, PLEASE USE A SEPARATE PACKAGE AND INCLUDE NAME, ADDRESS (WITH ZIP CODE) AND PHONE NUMBER OF YOUR FIREARM.**

- :: Record the serial number of your firearm before sending
- :: Pack your firearm for safety and to prevent further damage in shipping and handling. Preferably, ship in a firearm box. (Note: Original boxes may not be returned.)
- :: Remove all accessories from your firearm to prevent loss or damage.
- :: Ship your INSURED firearm by either UPS or Parcel Post. Remington is not responsible for damage or loss during shipment, so you may elect to purchase insurance from your carrier.

Serial Number:

125429

Model: 721



RE00074669

PWW=6/1950

BL Modification program. Sticky residue.  
Clean action, install new TA quote \$20.  
under Bolt lock modification program;  
FLS 12/30/03