

Remington Arms Company, Inc.

870 Remington Dr. P.O. Box 700

Madison, NC 27025-0700

Parts/Repairs

800-243-9700

Fax

336-548-7801

www.remington.com info@remington.com

REPAIR DOCUMENT

REPAIR DOCUMENT

Repair Order Number RE00048398	Description/Serial Number 6480116	Date Received - 6/21/2002
Account # - R-	Model 700 Center Fire Caliber: 300 WIN	Estimate Date -
	MAG BDL	Current Date - 6/28/2002
Customer JOSEPH AZZARELLO 110 PHLOX AVE METAIRIE, LA 70001 US		Return To JOSEPH AZZARELLO 110 PHLOX AVE METAIRIE, LA 70001 US
Phone (H) (504)-885-3101		Fax (504)-887-9278
Phone (W)		Email

Problems			
Reported		Found	
M123	FORWARD TO PRODUCT SERVICE FOR INSPECTION	M123	FORWARD TO PRODUCT SERVICE FO

Technician's Comments	
Problem/Notes	All three trigger adjusting screws altered. Replace trigger assembly at \$20.00 per DJS.

Parts and Labor			
Material #	Material Description	Quantity	Warranty (Y/N)
Part			
F26345	700 TRIG ASSB RH	1	Y
Part	Total:	1	
Service			
4000104	ARMS SERV SHIPPING & HANDLING	0	Y
4000116	GR-LABOR	20	N
4000119	GR-TEST	1	Y
4000294	GR-CHECK TPA	1	Y
Service	Total:	22	

10 LBS 1 OF 1


COD

REXINGTON ARMS CO INC
800 243-9700
14 HOEFER AVE
ILLION NY 13357

SHIP

TO:

JOSEPH AZZARELLO
110 PHLOX AVE
METAIRIE LA 70001




LA 700 0-03



UPS GROUND

TRACKING #: 1Z 114 813 72 1190 5342



BILLING: P/P
COD \$20.80

INV#: RE00048398

ASC 05.00 J69K/J64K 16.0A 01/2002