

11/17/90
Remington Arms Co. Inc
Arms Service Div.
14 Hoefler Ave
ILION NY. 13357

Remington Mod 700 BDL
Ser # A6588602 is being
returned for repair.

The rifle has discharged
on several occasions when
the safety has been moved
from S to F even though
my finger was off the
trigger. I have not tried
to make any alterations to
the trigger pull since I
have owned the rifle or even
had the action out of the
stock.

This condition causes me
great concern since an
accidental discharge could

occur any time the rifle
is being unloaded since
it has to be taken off
safe to unload.

Yours truly

JOHN BURNS
2199 S. 900. EAST
BOUNTIFUL UT 84010