

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER

R 94-02836

INITIAL CUSTOMER ORDER NO.

CALL TAG ATTN: DENNIS SANITA

PS

DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE
11/21/94	01/24/94	LH 2-87	B6847096		700 243 WIN ADL
ACCESSORIES W/STUDS					

FROM:

Field Supv
BROWN, DEE M.
RT 5 BOX E-29
VILLE PLATTE

LA 70586

SHIP TO:

BROWN, DEE M.
RT 5 BOX E-29
VILLE PLATTELA
70586

CUST NO: 091118 C.O.D L

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

059001

WRITE ☐

FROM DATE

ESTIMATED

VIA

UPS

GUN CONDITION

- ☐ NEW
☐ LIGHTLY WORN
☐ WORN
☐ VERY WORN
☐ UNREPAIRABLE
☐ MARRED

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

CYCLE

A1

B1

TRIGGER GROUP

B2

BOLT ASSY.

B3

BARREL ASSY.

B4

REC. ASSY.

B5

WOOD

C1

D3

METAL

C2

MAIN FAULT

Unable to duplicate customer concern. Examination revealed that the rifle needs a good cleaning, bolt body rusty, and more than normal force required to move safety assembly.

ARTS

COMMENTS

*Customer requests one change for m/700 pump in 243 caliber.
Agreed to change, as pattern of pump.*

Supply replacement m/700 243 cal (4653)

Rev #

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

Repair TA00N m/700 was to WIP

OFFICE COPY

RD6925 REV. 1/92

PS00889