

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER
R 93-27402

INITIAL CUSTOMER ORDER NO.

PS 2863

DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE
2/07/93	12/15/93	EU 10-71	6486770		700 30-06 ADL

ACCESSORIES W/STUDS SCOPE BASE L/REAR SIGHT

FROM:

SHIP TO:

BARTS SPORTS WORLD
6814 RITCHIE HWY
GLEN BURNIE

MD 21061

BARTS SPORTS WORLD
6814 RITCHIE HWY
GLEN BURNIEMD
21061

CUST NO: 002226 ILION L

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

PROM. DATE

ESTIMATED

VIA

1-11-94

UPS

GUN CONDITION

- ☐ NEW
☐ LIGHTLY WORN
☐ WORN
☐ VERY WORN
☐ UNREPAIRABLE
☐ MARRED

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

25.00

Product Service

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP		B2			E1	F1
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT

Upon receipt, rifle inspected, trigger would not reset. Gunner of the 1971 model rifle removed the action and trigger assembly as was with dirt and heavy sticky substance. Rust also found in trigger housing. Rifle had been poorly maintained.

COMMENTS

Replaced trigger assembly and clean action at 1/2 normal pressure. Cost as quoted of good work.

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6925 REV. 1/92

PS00950