

Jim,

I loaded a single round into this rifle to check sight alignment. I always keep the safety in safe position when loading & closing bolt. Preparing to fire I moved safety to "fire" position & rifle discharged. I then used the empty casing to see if it would fire again using the same sequence, & three times in a row it "fired" when safety moved to "fire" position. Have not been able to cause this to happen again after repeated tries.

Needless to say Jim a little nervous using the rifle now, no confidence in the safety of it. Since the safety has to be moved to the "fire" position to operate the bolt for unloading I decided to return the rifle to Remington for a thorough "check-up".

Also, the button in the trigger guard to release the bolt from the rifle has never functioned since the gun was new.

If it makes any difference, I was using handloads which are exactly the same loads I've used for years with no problem.

I hope you find a problem & can correct it. Please let me know what problem was found....

Thanks,

Stetson

address: on back
(over)

Robert L. Bartlett
Rt 1 Box 91AA
Ladbetter, TX. 78946
phone: 409-884-0641

Jim,

Have since talked to two other friends who know
someone with a model 700 that have had the same
problem.

B