

Remington.

Repair Form

(NOTE: Please print and complete this form, and then include it with your firearm.)

Model Number: 700	Serial Number: 6823156
Name: Tim Boyd	Date of Purchase: ??
Address (no PO Boxes): 200 White Pine Drive Box 81	
City: Cucumber	State: WV Zip: 24826
Phone (Daytime): 304-875-3840	Fax:
E-mail Address: pastort@earthlink.net	
Please describe your problem:	
Firing pin releases when bolt is engaged on occasion. Gun is eligible for bolt-lock Safety Modification Program also.	
Additional Information: (Ammo type, brand, handload specifications, etc.)	
NOTE: Prior to shipping your firearm, contact the Repair Center for services provided and estimated repair time.	
⚠ WARNING: DO NOT SEND LIVE OR SPENT SHELLS IN YOUR FIREARM OR IN THE SAME BOX WITH THE FIREARM. THIS IS A VIOLATION OF FEDERAL LAW. IF YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE SEND THEM IN A SEPARATE PACKAGE AND INCLUDE NAME, ADDRESS (WITH ZIP CODE), TELEPHONE AND MODEL AND SERIAL NUMBER OF YOUR FIREARM.	
<ul style="list-style-type: none">Record the serial number of your firearm before sending it.Pack your firearm for safety and to prevent further damage in shipping and handling. Preferably, ship in a firearm box. (Note: Original boxes may not be returned.)Remove all accessories from your firearm to prevent loss or damage.Ship your INSURED firearm by either UPS or Parcel Post. Remington is not responsible for damage or loss during shipment, so you may elect to purchase insurance from your carrier.	

Serial Number: 6823156

Model: 700



RE00094854

could not duplicate concern.
TRIP. ASSM. Dirty/sticky +
PARTS work sluggish. Replace
TPA under bolt lock program
\$20.00
Quote

form.htm

3/11/2005