

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER
R 92-15194

INITIAL CUSTOMER ORDER NO.

JJM

DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE
07/16/92	07/28/92	EC 10-82	B6415937		700 30-06 BDL

ACCESSORIES

W/STUDS

FROM:

BOWLER, DWIGHT E
813 CHARLES
YPSILANTI

MI 48198

SHIP TO:

BOWLER, DWIGHT E
813 CHARLES
YPSILANTIMI
48198

CUST NO: 064175

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	CLEAN/TEST	PROM. DATE	ESTIMATED	VIA
						UPS

IN CONDITION	REPAIR CHARGE
NEW	EXCISE
LIGHTLY WORN	TAX
WORN	INSURANCE
VERY WORN	UPS
UNREPAIRABLE	PARCEL POST
MARRED	TOTAL

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CLE	A1	B1				
IGGER GROUP		B2			E1	F1
LT ASSY.		B3			E2	F2
REL ASSY.		B4			E3	F3
C. ASSY.		B5		D2	E4	F4
DOD			C1	D3	E5	F5
ETAL			C2			

N FAULT *Cannot duplicate complaint. Rifle operates normally in every respect. The only thing that was noted is that trigger moving is somewhat slow - there is an excess of oil inside the assembly. trigger pull - 4 1/2 pounds; rear lock - .013"*

ITS COMMENTS *We can clean present trigger assembly and return, or, we can ~~replace~~ replace the trigger assembly at ~~the~~ the shop. We are a group of good-will, and that will better restore confidence in the rifle.*

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 1/92

PS00987