

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER
R 92-04099

INITIAL CUSTOMER ORDER NO.

JJM F79535

DATE RECEIVED

DATE OPENED

DATE CODE

SERIAL NUMBER

NEW SERIAL NUMBER

MODEL AND GRADE

01/28/92

02/03/92

KF 5-85

B6587087

700 270

EDL

ACCESSORIES

W/STUDS

SCOPE BASE

FROM:

SHIP TO:

BORDER SPORTING GOODS INC
303 MAHER STREET
LAREDO TX 78041BORDER SPORTING GOODS INC
303 MAHER STREET
LAREDO TX 78041

CUST NO: 006546 C.O.D.

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

CLEAN/TEST

PROM. DATE

ESTIMATED

VIA

2-25-92

UPS

GUN CONDITION

☐ NEW☐ LIGHTLY WORN☐ WORN☐ VERY WORN☐ UNREPAIRABLE

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

CYCLE

A1

B1

TRIGGER GROUP

BOLT ASSY.

BARREL ASSY.

REC. ASSY.

WOOD

METAL

Fires when Bolt is lifted

B3

B4

B5

C1

C2

E1

E2

E3

E4

E5

F1

F2

F3

F4

F5

MAIN FAULT

Carry over duplicate complaint. However, disassembly of rifle revealed rear engagement has been improperly adjusted about factory, as evidenced by broken sealant - rear engagement is excessive.

Trigger pull - 4 3/4 pounds; rear lift .013"

PARTS

COMMENTS

Offer new trigger assembly at 1/2 retail cost, as a gesture of good-will.

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6925 REV. 8/91

PS00996