

RECEIVING AND ESTIMATING REPORT

COMMENTS

INITIAL

CUSTOMER ORDER NO.

LEZ

DATE RECEIVED

DATE OPENED

DATE CODE

SERIAL NUMBER

MODEL AND GRADE

ORDER

12/18/90

12/21/90

XC 12-82

A6533952

700

243

BDL

R

90-33595

ACCESSORIES

W/STUDS

L/SIGHTS

FROM:

BAELL MERCANTILE CO. INC.
550 FIRST ST. N.E.
MOULTRIE GA 31768

SHIP TO:

BAELL MERCANTILE CO. INC.
550 FIRST ST. N.E.
MOULTRIE GA
31768

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

CLEAN/TEST

PROM. DATE

ESTIMATED

VIA

UPS

REPAIR CHARGE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

GUN CONDITION:

☐ NEW

☐ SLIGHTLY WORN

☐ VERY WORN

☐ MISUSED

☐ MARRED

CUSTOMER'S REQUEST

MAIN FAULT

fire - bolt is spent
Cannot duplicate complaint - Trigger pull 5 1/2 pounds, rear lift .0095". However, trigger return is somewhat slow, as trigger assembly is contaminated with sticky oil (?) residue. Suggest gun maintenance.

PARTS

Offer to clean present trigger assembly (if possible) or, we can replace it at a normal cost, as a gesture of good will, if it will both restore confidence in the rifle.

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

RD6925 REV. 7/90

PS01033