

RECEIVING AND ESTIMATING REPORT

CUST NO: 050232 C.O.D

COMMENTS

STT:KO

TIAL CUSTOMER ORDER NO.

CS

TE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	MODEL AND GRADE	ORDER
9/27/91	10/02/91	WU 8-71	6471674	700 30-06 BDL	R 91-19510

CESSORIES W/STUDS

L/REAR SIGHT

OM:

SHIP TO:

BOURGEOIS, RODNEY
6 LA COMBE HARBOR LA
PO BOX 907
LA COMBE
USA

LA 70445

BOURGEOIS, RODNEY
6 LA COMBE HARBOR LA
PO BOX 907
LA COMBE
USA

LA 70445

COUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

CLEAN/TEST

PROM. DATE

ESTIMATED

VIA

10/2/91

UPS

AIR CHARGE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

IN CONDITION:

☐ NEW☐ SLIGHTLY WORN☐ VERY WORN☐ MISUSED☐ MARRED

STOMER'S REQUEST

1) When attempting to move the safety from safe to fire and a sound is in the chamber, the weapon automatically fires. 2) After firing a round and another is bolted the weapon may or may not fire as soon as the bolt is fully closed."

must duplicate complaints. However, it was noted upon removal of action from stock, the trigger assembly has some rust (both internally & externally) trigger assembly has been improperly adjusted out of factory - excessive over-travel trigger pull measured at 3 pounds; rear sight "007"

Due to condition of present trigger assembly, and customer's ~~comments~~ comments re: bolt - lock, offer new - style (no bolt - lock) trigger assembly at $\frac{1}{2}$ normal cost, as a gesture of good will.

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6925 REV. 7/90

PS01049