

(E) XACT 10/02/78
08 59 5

9-20-91

MODEL: 700
GA/CAL: 30-06
TYPE: BDL
ACCESSORIES: W/STUDS

Phone:
(504) 882-7392

Remington Arms Co, Inc
Arms Service Div.
Ipswich, New York, 13357

IS: WU 8-71
IER ACCESSORIES:
REAR SIGHT

Dear Sirs, Sen. # 6471674

I purchased the accompanying
model 700 BDL 30-06 in approx. 1972.

At the time and to date, the
only way to clear a round from
the chamber is to put the safety
on fire and then work the bolt.

I have never felt comfortable
with this procedure. Is this
normal? Please reply.

CAROL M.

During our last hunting
season the weapon began
acting strangely and dangerously.
The problems are:

1. When attempting to move
the safety from safe to fire
and a round is in the chamber,
the weapon automatically fires.

FROM

PACKAGE ID. NO.

142025



(E) XACT 10/02/9
08 59 50
MODEL: 700
GA/CAL: 30-06
TYPE: BDL
ACCESSORIES: W/STUDS

This is most disconcerting and dangerous.
It does not, however, do this
every time.

ES: WU 8-71
HER ACCESSORIES:
REAR SIGHT

2. After firing a round and
another is bolted, the weapon
may or may not fire as
soon as the bolt is fully
closed - very dangerous

ENTERED BY: LCS
REPAIRMAN:
TYPIST:
CORRESPONDENT:
PFC = PRINT RCT

Please correct (repair)
Nos. 1 & 2 as above. If a
retrofit is available to allow
ejecting a round while still
on safe, please do so.

CAROL M.

I don't need an estimate - just
let me know how much

Rodney M. Bourgeois
6 La Combe Harbor Lane, P.O. Box
La Combe, La 70445 907

many thanks
Rodney M. Bourgeois

