

RECEIVING AND ESTIMATING REPORT

POST NO: 001675 WILM

ATTN J STEKE
STAINLESS STEEL

INITIAL
JH 0339

DATE RECEIVED 07/15/91	DATE OPENED 07/17/91	DATE CODE LU 2-71	SERIAL NUMBER 6412789	MODEL AND GRADE 700 17REM BDL	ORDER 91-14099
ACCESSORIES W/STUDS		SCOPE BASE		L/SIGHTS	

FROM:

BLYTHE'S SPORT SHOP, INC
2810 N. CALUMET AVE
GEORGE HARTRUNFT
VALPARAISO
USA

IN 46383

SHIP TO:

BLYTHE'S SPORT SHOP, INC
2810 N. CALUMET AVE
GEORGE HARTRUNFT
VALPARAISO
USA

IN 46383

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	CLEAN/TEST	PROM. DATE	ESTIMATED	VIA UPS
----------------	--------------------	--------------------------------	------------	------------	-----------	------------

REPAIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL
---------------	-----	-----------	-----	-------------	-------

GUN CONDITION:

☐ NEW

☐ SLIGHTLY WORN

☐ VERY WORN

☐ MISUSED

☐ MARRED

CUSTOMER'S REQUEST

"this rifle is seen firing when bolt is shut"

MAIN FAULT

As received, rifle would not fire — pulling trigger would not release firing pin. Trigger assembly has been improperly adjusted outside factory, as evidenced by missing sealant on adjustment screws — 1) insufficient over-travel, 2) Trigger pull below spec at 2#, 3) cam engagement insufficient

Offer new trigger assembly at 1/2 normal cost, as gesture of good-will.

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE