

7/21/92

TO: ARMS SERVICE
FROM: PRODUCT SERVICE

SUBJECT: R# 91-27077; M/700 270WIN; S.N. 6522201
DENNIS BERNHARDT

The customer has accepted offer to replace trigger assembly in subject rifle at no-charge.

- 1.) Install a new no bolt-lock safety trigger assembly in rifle
- 2.) Thoroughly clean all rusted areas of rifle and properly lubricate
- 3.) Return rifle to owner — do not charge handling or return shipping.

Thank you,
JLS