

Remington Arms Company, Inc.

870 Remington Dr. P.O. Box 700

Madison, NC 27025-0700

Parts/Repairs
Fax

800-243-9700
336-548-7801

www.remington.com info@remington.com

REPAIR DOCUMENT

REPAIR DOCUMENT

Repair Order Number RE00064474 Account # - R-	Description/Serial Number 6263670 Model 700 Center Fire Caliber: 7MM MAG ADL W/SS BARREL	Date Received - 5/6/2003 Estimate Date - 4/22/2003 Current Date - 5/9/2003
Customer BIG RIVER DOG SUPPLY 2093 SILVER STREET HINESBURG, VT 05461 US		Return To BIG RIVER DOG SUPPLY 2093 SILVER STREET HINESBURG, VT 05461 US
Phone (H) (802)-482-3028 Phone (W)		Fax Email

Problems			
Reported		Found	
M123	FORWARD TO PRODUCT SERVICE	M123	FORWARD TO PRODUCT SERVICE FO
	FOR INSPECTION	M238	CLEAN & INSPECT
M994	FIRED ON SAFETY	M239	REPLACE TRIGGER ASSEMBLY

Technician's Comments	
ProblemNotes	Trigger assembly extremely dirty, coated with a sticky residue. Settings altered. Quote \$20.00 for a new trigger assembly and cleaning action under Bolt Lock Modification Program. FLS 4/22/03.

Parts and Labor			
Material #	Material Description	Quantity	Warranty (Y/N)
Part			
F26345	700 TRIG ASSB RH	1	Y
Part	Total:	1	
Service			
4000104	ARMS SERV SHIPPING & HANDLING	0	Y
4000116	GR-LABOR	20	N
4000118	GR-CLEAN	1	Y
4000119	GR-TEST	1	Y
Service	Total:	22	