

Remington

TRACKING DOCUMENT



Repair Order Number

Repair Order Number RE00056288	Description/Serial Number ML211324	Repairman - Dale Lewis Date Received - 12/11/2002
Account # - R-	Model 700ML Center Fire Caliber: 50	Estimate Date - 11/26/2002
		Current Date - 4/1/2003
Customer JOHN BLOODGOOD 5507 RIDGE RD MOUNT AIRY, MD 21771 US		Return To JOHN BLOODGOOD 5507 RIDGE RD MOUNT AIRY, MD 21771 US
Phone (H) (301)-471-3886 Phone (W)		Fax Email

Reported		Problems Found	
M992	FIRES WHEN SAFE RELEASED	M123	FORWARD TO PRODUCT SERVICE P

Material #		MaterialDesc	Quantity Needed	Quantity From Inv	Quantity From Kit	Warranty (Y/N)
Part						
F99294		700 ML SS TRIG ASSB	1	1	0	Y
Part Total:			1	1	0	
Service						
4000294		GR-CHECK TPA	1	1	0	Y
4000104		ARMS SERV SHIPPING & HANDLING	0	0	0	Y
4000119		GR-TEST	1	1	0	Y
Service Total:			2	2	0	

ProblemNotes	broken connector,install new trig assm n/c per product service				
Repairman	Proof	Clean	Test	Target	Pattern
Gallery Tester	Date	Date	Date	Date	Date