

### Repair Order Number

VE 229 101 227 48



|                                                                                                          |                                              |                                                                                                           |
|----------------------------------------------------------------------------------------------------------|----------------------------------------------|-----------------------------------------------------------------------------------------------------------|
| <b>Repair Order Number</b><br>RE00067527                                                                 | <b>Description/Serial Number</b><br>A6646010 | <b>Repairman -</b> Dale Lewis                                                                             |
| <b>Account # - R-</b>                                                                                    | <b>Model 700 Caliber:</b> 7 MM MAG BBLD      | <b>Date Received -</b> 7/10/2003                                                                          |
|                                                                                                          | <b>ACT AND BOLT ONLY</b>                     | <b>Estimate Date -</b>                                                                                    |
|                                                                                                          |                                              | <b>Current Date -</b> 9/23/2003                                                                           |
| <b>Customer</b><br>ISTVAN BERCZI DVM PHD<br>79 DAWSON ROAD<br>BOX 143A RR#2<br>LORETTE, MB. XX R0AOYO CA |                                              | <b>Return To</b><br>ISTVAN BERCZI DVM PHD<br>79 DAWSON ROAD<br>BOX 143A RR#2<br>LORETTE, MB. XX R0AOYO CA |
| <b>Phone (H)</b> (204)-878-3586                                                                          | <b>Fax</b> (204)-789-3996                    |                                                                                                           |
| <b>Phone (W)</b> (204)-789-3320                                                                          | <b>Email</b> berczil@ms.umanitoba.ca         |                                                                                                           |

| Problems |                                           |       |                                |
|----------|-------------------------------------------|-------|--------------------------------|
| Reported |                                           | Found |                                |
| M123     | FORWARD TO PRODUCT SERVICE FOR INSPECTION | M123  | FORWARD TO PRODUCT SERVICE FOR |
| M990     | DISCHARGED WHEN UNDOING SAFETY            | M240  | BOLT LOCK SAFETY MODIFICATION  |
| M992     | MISFIRED                                  |       |                                |

| Repair            |                               |                            |                              |                              |                           |
|-------------------|-------------------------------|----------------------------|------------------------------|------------------------------|---------------------------|
| <u>Material #</u> | <u>MaterialDesc</u>           | <u>Quantity<br/>Needed</u> | <u>Quantity<br/>From Inv</u> | <u>Quantity<br/>From Kit</u> | <u>Warranty<br/>(Y/N)</u> |
| Part              |                               |                            |                              |                              |                           |
| F26345            | 700 TRIG ASSB RH              | 1                          | 1                            | 0                            | Y                         |
| Part Total:       |                               | 1                          | 1                            | 0                            |                           |
| Service           |                               |                            |                              |                              |                           |
| 4000104           | ARMS SERV SHIPPING & HANDLING | 0                          | 0                            | 0                            | Y                         |
| 4000116           | GR-LABOR                      | 20                         | 20                           | 0                            | N                         |
| 4000119           | GR-TEST                       | 1                          | 1                            | 0                            | Y                         |
| 4000294           | GR-CHECK TPA                  | 1                          | 1                            | 0                            | Y                         |
| Service Total:    |                               | 22                         | 22                           | 0                            |                           |

10-30  
P-10K4  
\$ 24.25  
7.2 LBS

**ProblemNotes** as rec'd trigger does not properly return under sear every time.install new ta,clean action \$20 U.S. under bolt lock safety modification program.

|                |       |       |      |        |         |
|----------------|-------|-------|------|--------|---------|
| Repairman      | Proof | Clean | Test | Target | Pattern |
| Gallery Tester | Date  | Date  | Date | Date   | Date    |