

RECEIVING AND ESTIMATING REPORT

COMMENTS

INITIAL CUSTOMER ORDER NO.

JJM 1487

DATE RECEIVED 10/23/90	DATE OPENED 10/25/90	DATE CODE XL 12-64	SERIAL NUMBER 132398	MODEL AND GRADE 700 30-06 ADL	ORDER R 90-20126
---------------------------	-------------------------	-----------------------	-------------------------	----------------------------------	---------------------

ACCESSORIES

FROM:

B & R GUNS
11 W. SAINT JOSEPH ST
PERRYVILLE MO 63775

SHIP TO:

B & R GUNS
11 W. SAINT JOSEPH ST
PERRYVILLE MO
63775

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	CLEAN/TEST	PROM. DATE	ESTIMATED	VIA UPS
----------------	--------------------	--------------------------------	------------	------------	-----------	------------

REPAIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL
---------------	-----	-----------	-----	-------------	-------

GUN CONDITION:

☐ NEW

☒ SLIGHTLY WORN

☐ VERY WORN

☐ MISUSED

☐ MARRED

CUSTOMER'S REQUEST

"The customer said he has a problem that the rifle would shoot holding it in the horizontal position and when he propped it up to remove the ammo the shell went off".

MAIN FAULT

Could not duplicate above complaint. However, it was noted that firing pin fell somewhat slow. Removal of stock disclosed that trigger assembly is contaminated with solidified oil(?) and dirt. Cold temperatures could possibly aggravate this condition.

PARTS

Send repair quotation to replace trigger assembly at 1/2 normal price, as gesture of good-will.

Rifle is 26 years old

REPAIRMAN BW	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

RD6925 REV. 7/90

PS01189

PURCHASE ORDER

1487

B & R GUNS
11 W. St. Joseph Street
PERRYVILLE, MISSOURI 63775

(314) 547-2100

DATE 13 Oct 90	REQ. NO.
SHIP TO	

ORDER
R 90-28126

Remington Arms Co. Inc.
1007 Market Street
Wilmington DE 19898

NS
INT JOSEPH ST
LE MD
63775

IN SHIP	SHIP VIA	F.O.B. POINT	TERMS	
ORDERED	QTY. RECEIVED	DESCRIPTION	PRICE	AMOUNT
Please fix the enclosed Remington 700 30-06 S# 132398. The customer said he has a problem that the rifle won't shoot. Holding it in the horizontal position + when he pointed it up to remove the ammo the shell went off.				
Thanks				

ESTIMATED	VIA UPS
CEL POST	TOTAL
USED	☐ MARRED
it shot holding it up to remove the	
s noted that firing that trigger assembly temperature could	

Please send _____ copies of your invoice.
Please show this Purchase Order Number on all packages and invoices.
Notify us immediately if you are unable to ship as specified.

D. Doran
Authorized by

trably aggravate this condition.

Send repair quotation to replace trigger assembly at 1/2 normal price, as gesture of good-will.	
Rifle is 26 years old	
REPAIRMAN <i>BW</i>	PROOF
GALLERY TESTER	DATE
CLEAN	DATE
TEST	DATE
TARGET	DATE
PATTERN	DATE

OFFICE COPY

RD6925 REV. 7/90

PS01190