

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER
R 94-13175

STAINLESS/CUSTOMER REMOVED BLUEING

INITIAL FPS	CUSTOMER ORDER NO.		DATE RECEIVED 04/14/94		DATE OPENED 04/15/94	DATE CODE PU 6-71	SERIAL NUMBER 6445063	NEW SERIAL NUMBER	MODEL AND GRADE 700 17 REM	BDL
ACCESSORIES W/STUDS		L/SIGHTS								

FROM:

BUTTON, DENNIS
13860 GILLETTE RD
ALBION

NY 14411

SHIP TO:

BUTTON, DENNIS
13860 GILLETTE RD
ALBION

NY
14411

CUST NO: 096024 C10.D

ACCOUNT NUMBER 063103	ACCOUNT NUMBER N/C	PROM. DATE	ESTIMATED	VIA UPS
GUN CONDITION		REPAIR CHARGE 20.00		
☐ NEW ☐ LIGHTLY WORN ☒ WORN ☐ VERY WORN ☐ UNREPAIRABLE ☐ MARRED		EXCISE TAX INSURANCE UPS 8.00 PARCEL POST TOTAL 28.00		

Send quote

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP						
BOLT ASSY.		B3				F1
BARREL ASSY.		B5				F2
REC. ASSY.				D2	E4	F3
WOOD			C1	D3	E5	F4
METAL			C2			F5

Fixed on safe return usually after having set for a long period of time

MAIN FAULT *Mfg. 6-71 Unable to duplicate customer concern as recd. Trigger pull and cocking adjustment screws were altered outside of factory, seal was gummy and sticking in housing, exchange trigger assy. at special price as gesture of good will and to restore customer confidence in repl.*

PARTS	COMMENTS
	<i>Trigger pull measured 4 1/2 to 6# as recd. seal left was .010</i>
	<i>Blueing has been removed from Bolt Assy</i>

REPAIRMAN JAL	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 1/94