

DEAR SIR,

THIS GUN IS USED VERY LITTLE, MOSTLY IN LATE FALL AND WINTER WHILE PREDATOR CALLING. THE ACCIDENTAL DISCHARGES SEEM TO OCCUR WHEN THE RIFLE HAS SAT DORMANT FOR LONG PERIODS OF TIME AND ALWAYS WITH THE VERY FIRST ROUND CHAMBERED.

I HAVE JUST RECENTLY TAKEN THE BLUING OFF THIS RIFLE BECAUSE IT WAS BADLY WORN. I FOUND OUT THAT IT IS STAINLESS AND CAN'T GET IT REBLUED LOCALLY,

Dennis Button
13860 Dullette Road
Allison, N.J. 14411

MODEL 700 17 CAL.
SERIAL No 6445063

PS01213