

3/21/94

M/100 #6304601

M/9/10

Condition - Worn

Upon receipt unable to duplicate any of the customer mentioned
problems. Tugger not very responsive, feels very loose

TP measured 2 1/2 lbs

51 .005

Both allow run inspection

Rel contact on Tugger adjustment screws

Customer both mention that a gunsmith repaired.

Hold original TPA in Prod. Service