

1700 Bloomington Road
East Peoria, IL 61611

April 20, 1994

Remington Arms Company
Arms Service Division
14 Hoefler Ave.
Ilion, NY 13357

TO WHOM IT MAY CONCERN:

The enclosed Model 700 Varmint BDL ~~gun~~ Remington (serial # 6213521) was purchased (used) in June of 1992. (Sales receipt is attached.) This gun is being returned for corrections to the firing mechanism.

This gun has already misfired. In the summer of 1993, my brother-in-law (Joseph Slyman) went to unload the gun and took off the safety. The gun fired. At the time, I was sure that Joe must have touched the trigger, but Joe swore he didn't. (Joe is not a novice at handling fire arms, however now after having viewed the 60 minutes segment, I realize that it's probable that the gun is at fault.) Fortunately, all that happened was that it blew a hole in my gun case. I don't think it's necessary to ponder about what the possible ramifications could have been! We are indeed fortunate that no one was in the immediate proximity.

I would like this defect fixed. However, I do not expect to have to pay for this correction. If there is going to be an associated charge, please let me know. At that point I would consider drawing attention to this problem, and I would not have any qualms about signing a legal affidavit attesting to the validity of the above stated situation.

I have experienced first hand the power of this gun, therefore, I realize how dangerous this problem is if it goes unchecked. Please contact me with any questions.

Sincerely,



Michael A. Young.