

RECEIVING AND ESTIMATING REPORT

COMMENTS

product service

ORDER R 93-24598

INITIAL **JJM** CUSTOMER ORDER NO. **7850**

DATE RECEIVED **11/09/93** DATE OPENED **11/14/93** DATE CODE **PZ 6-75** SERIAL NUMBER **6873788** NEW SERIAL NUMBER MODEL AND GRADE **700 300WIN** MAG/BDL

ACCESSORIES **W/STUBS** SCOPE BASE **L/REAR SIGHT**

FROM: *[Signature]* **CHALMETTE JEWELRY & SPTG GOODS**
507 W ST BERNARD HWY
CHALMETTE LA 70043

SHIP TO: **CHALMETTE JEWELRY & SPTG GOODS**
507 W ST BERNARD HWY
CHALMETTE LA 70043

CUST NO: 001988 C.O.D.

ACCOUNT NUMBER ACCOUNT NUMBER N/C

WRITE ☐

PROM. DATE ESTIMATED **12-2-93** VIA **UPS**

- GUN CONDITION
- ☐ NEW
 - ☐ LIGHTLY WORN
 - ☐ WORN
 - ☐ VERY WORN
 - ☐ UNREPAIRABLE
 - ☐ MARRED

REPAIR CHARGE **25.00**
 EXCISE
 TAX
 INSURANCE
 UPS
 PARCEL POST
 TOTAL

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE		B1				
TRIGGER GROUP		B2			E1	F1
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT *Left mfg 1975 Upon receipt I wanted to inspect Customer concern. Examination revealed that the action and trigger assembly are covered with sticky substance, which has been dripping off the receiver. The bolt stop release is jammed up and does not return. Rifle has been for some*

COMMENTS *Left mfg 1975 Upon receipt I wanted to inspect Customer concern. Examination revealed that the action and trigger assembly are covered with sticky substance, which has been dripping off the receiver. The bolt stop release is jammed up and does not return. Rifle has been for some*

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
<i>[Signature]</i>					
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 1/92

PS01304