

CARROLL'S GUN SHOP, INC.

1612 N. Alabama Rd.
Wharton, Texas 77488
532-3175
9-532-2810

Number: 6481776

Model: 700



RE00051391

Date Code
RU 11/71

Repair Order No.

#R-245

Date: Aug. 15, 2002

Enclosure:

Remington M-700 BDL, 270 win. cal. rifle, Ser. #6481776

Repair Order:

Please modify as per safety update.

Our customer states that he has had two accidental discharges.

51391

Estimate Request:

- Please
- Only if not covered by Warranty
- Only if charges are over \$ _____
- Not Necessary

We feel Item is:

- Covered by warranty
- Not covered by Warranty
- Unable to determine

Signed:

Olivia Konwicka

Open Account

9/4/02
Action & trigger assembly
What powder substitutions on action.
For maintenance
Replace trigger assembly \$20.00
as usual