



TRACKING DOCUMENT

Repair Order Number



Repair Order Number

RE00051262

Description/Serial Number

B6340120

Repairman - Robert Frink

Date Received - 9/16/2002

Account # - R-

Model 700 Center Fire Caliber: 3006
BDL

Estimate Date - 8/28/2002

Current Date - 9/18/2002

Customer

CHAPEL SPORTS LTD
116 20 ATLANTIC AVENUE

RICHMOND HILL, NY 11419 US

Return To

CHAPEL SPORTS LTD
116 20 ATLANTIC AVENUE

RICHMOND HILL, NY 11419 US

Phone (H) (718)-847-7661

Phone (W)

Fax

Email

Problems

Reported

M123 FORWARD TO PRODUCT SERVICE
FOR INSPECTION
M993 FIRES ON SAFE

Found

M123 FORWARD TO PRODUCT SERVICE F
M238 CLEAN & INSPECT
M239 REPLACE TRIGGER ASSEMBLY

Repair

<u>Material #</u>	<u>MaterialDesc</u>	<u>Quantity Needed</u>	<u>Quantity From Inv</u>	<u>Quantity From Kit</u>	<u>Warranty (Y/N)</u>
Part					
F26345	700 TRIG ASSB RH	1	1	0	Y
Part Total:		1	1	0	
Service					
4000104	ARMS SERV SHIPPING & HANDLING	0	0	0	Y
4000116	GR-LABOR	20	20	0	N
4000118	GR-CLEAN	1	1	0	Y
4000119	GR-TEST	1	1	0	Y
Service Total:		22	22	0	

ProblemNotes

Replace trigger assembly, clean action. Quote \$20.00 under Bolt Lock Modification Program.
Could not duplicate concern. Trigger assembly coated with sticky residue. FLS 8/28/02.

Repairman	Proof	Clean	Test	Target	Pattern
Gallery Tester	Date	Date	Date	Date	Date


10 LBS 1 OF 1

REXINGTON ARMS CO INC
800 243-9700
14 HOEFLER AVE
ILION NY 13357

SHIP

TO:

CHAPEL SPORTS LTD
116 20 ATLANTIC AVENUE
RICHMOND HILL NY 11419




NY 111 9-02



UPS GROUND

TRACKING #: 1Z 114 813 03 1194 6482



BILLING: P/P

INV#: RE00051262

ASC 05.00 J69X/J64X 15.0A 01/2002