

Repair Order Number



Repair Order Number  
RE00051222

Description/Serial Number  
6727796

Repairman - Herb Brown  
Date Received - 8/29/2002

Account # - R-

Model 700 Center Fire Caliber: 3006  
BDL LH

Estimate Date - 8/28/2002

Current Date - 10/14/2002

Customer  
COOKS SPORTLAND  
6363 N MONROE

Return To  
COOKS SPORTLAND  
6363 N MONROE

MONROE, MI 48162 US

MONROE, MI 48162 US

Phone (H) (734)-242-0774

Fax

Phone (W)

Email

### Problems

#### Reported

M238 CLEAN & INSPECT  
M992 FIRES WHEN SAFE RELEASED  
M993 CLEAN COPPER OUT OF BBL

#### Found

M123 FORWARD TO PRODUCT SERVICE  
M178 TRIG ADJ SCREWS RESET, CANNOT

### Repair

#### Material # MaterialDesc

Quantity  
Needed

Quantity  
From Inv

Quantity  
From Kit

Warranty  
(Y/N)

#### Part

F32895 700 TRIG ASSB LH

Part Total:

1 1 0  
1 1 0

#### Service

4000294 GR-CHECK TPA  
4000104 ARMS SERV SHIPPING & HANDLING  
4000116 GR-LABOR  
4000118 GR-CLEAN  
4000119 GR-TEST

Service Total:

1 1 0  
0 0 0  
1 1 0  
1 1 0  
1 1 0  
4 4 0

#### ProblemNotes

Trigger adjusting screws altered. Replace trigger assm. \$20.00.

Repairman

Proof

Clean

Test

Target

Pattern

Gallery Tester

Date

Date

Date

Date

Date


10 LBS 1 OF 1

REMINGTON ARMS CO INC  
800 243-9700  
14 HOEFER AVE  
ILLION NY 13357

SHIP

TO:

COOKS SPORTLAND  
6363 N MONROE  
MONROE MI 48162




MI 482 0-00



UPS GROUND

TRACKING #: 1Z 114 813 03 1196 2893



BILLING: P/P

INV#: RE00051222

ASC 05.00 J69X/J64X 16.0A 01/2002