

File Number:	17960		Arms Service number:	51552	
Last Name:	C R PEDERSEN AND SON		First Name:		
Street:	2717 PERE MARQUETTE HWY		City:	LUDINGTON	
State:	MI	Zip:	49431	Home Ph:	
Work Ph:	231-843-2061	Product Type:	F	F A T O	
Type Concern:	S	PI PD P S	Concern Code:	1019	
Concern:	FIREARM COMPONENT DAMAGED				
Cause Code:	4040	Cause:	OTHER - UNSPECIFIED OR UNDETERMINED		
Assigned To:	SUPRY	Classification:	UND	UNJ UNC UND J	
Settlement Detail:	INSTALL NEW TA N/C		Settlement Amount:	\$65.00	
Date Opened Rem:	9/6/2002	Date Opened by P/S:	9/9/2002	Caliber:	50
Date of Incident:		Date Closed:	9/11/2002	Bullet Weight:	
Date to Analysis:		Date from Analysis:		Manufacturer:	
Model:	700	Serial:	ML241169	Date Code:	
Date Mfgd:	8/28/2001				
RAMAC:	700	Litigation:	☐	PreLitigation:	☐
Obsolete:	☐				
Custody:		Comments:	Customer said sear broke in trigger. TA total disassembled and not broken parts found. Unable to determine what customers concern was. Install new TA n/c. Repair and shipping documents 9/12/02.		
Time of Modification:	9:36:18 AM				
Date of Modification:	9/11/2002				