

Repair Order Number



Repair Order Number RE00051552	Description/Serial Number ML241169	Repairman - Robert Frink Date Received - 9/6/2002
Account # - R-	Model 700ML Center Fire Caliber: 50 SS LESS STOCK	Estimate Date - Current Date - 9/10/2002
Customer C R PEDERSEN AND SON 2717 S PERE MAROQUETTE HWY LUDINGTON. MI 49431 US	Return To C R PEDERSEN AND SON 2717 S PERE MAROQUETTE HWY LUDINGTON. MI 49431 US	
Phone (H) (231)-843-2061 Phone (W)	Fax (231)-845-7695 Email	

Reported		Problems Found	
M990	TRIGGER SEAR BROKE	M123	FORWARD TO PRODUCT SERVICE F

Material #		MaterialDesc	Quantity Needed	Quantity From Inv	Quantity From Kit	Warranty (Y/N)
Part						
F99294		700 ML SS TRIG ASSB	1	1	0	Y
Part Total:			1	1	0	
Service						
4000104		ARMS SERV SHIPPING & HANDLING	0	0	0	Y
Service Total:			0	0	0	

ProblemNotes		Trigger assembly removed - not broken. Undetermined what problem is. Install new trigger assembly at no charge. FLS 9/10/02.			
Repairman	Proof	Clean	Test	Target	Pattern
Gallery Tester	Date	Date	Date	Date	Date


8 LBS 1 OF 1

REMINGTON ARMS CO INC
800 243-9700
14 HOEFLER AVE
ILION NY 13357

SHIP

TO:

C R PEDERSEN AND SON
2717 S PERE MARQUETTE HWY
LUDINGTON MI 49431




MI 494 3-00



UPS GROUND

TRACKING #: 1Z 114 813 03 1193 9829



BILLING: P/P

INV#: RE00051552

ASC 05.00 J69K/J64K 16.0A 01/2002