

By: Bruce Travis Sr.

FIREARM INSPECTION WORKSHEET

BACKGROUND

Customer name: Crown Enterprises

R.E. Number: 84535

Reason for inspection: fix w/ safety on

FIREARM

Manufacturer: Rem. Model: 700

Serial Number: A6436078 Date of Manufacture: 4/77

Overall external condition: worn

Barrel condition: okay

Receiver condition: okay

Stock condition: okay

Bolt/firing pin condition: okay

Trigger assembly condition: parts work sluggish

Engagement: altered

Adjustments/alterations: altered

Other: bolt lock safety -

Headspace: -

Function evaluation:

Feeding: —

Extraction/ejection: —

Trigger pull: 3#

Manual safety: okay

Test firing results (if applicable): —

DISPOSITION

trig. assm. dirty and has a sticky lubrication

residue cause parts to work sluggish. Replace
complete TPA under light lock safety program & clean action

ADDITIONAL COMMENTS

Quote