

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER
R 94-01838

INITIAL CUSTOMER ORDER NO.

LJM

DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE
01/13/94	01/14/94	LD 2-77	A6424168		600 243
ACCESSORIES			W/STUDS SCOPE BASE		

MOHAWK

FROM:

SHIP TO:

CARROLLS GUN SHOP
1612 N ALABAMA RD
WHARTON

TX 77488

CARROLLS GUN SHOP
1612 N ALABAMA RD
WHARTONTX
77488

CUST NO: 006416 WILM

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

PROM. DATE

ESTIMATED

VIA

UPS

GUN CONDITION

- ☐ NEW
☐ LIGHTLY WORN
☐ WORN
☐ VERY WORN
☐ UNREPAIRABLE
☐ MARRED

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

20.00

Product Service

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP	"	B2			E1	F1
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4			E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT

Upon receipt, could not duplicate Customer Concern. However, examination of action and trigger assembly reveal that this rifle has been properly maintained. The action is dirty, the trigger assembly covered with gunning substance. Bolt stop release would not reset. Trigger housing moved at rear.

PARTS	COMMENTS				
substance. Bolt stop release would not retract. Trigger housing moved at user's.	Clean action & replace complete trigger assembly at 1/2 normal replacement cost, as per letter of good will.				
REPAIRMAN	PROOF	CLEAN	TEST	RESET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 1/92

PS01359