

Serial
Number:

A6281132

Model: 700



RE00074538

Could not duplicate. Sticky residue - trigger return
Sluggish. Quote \$20 for new TA and cleaning action
under the bolt lock modification program.

FCS 11062004

12-15-03

Dear Remington:

74538

A1=3/76

Please go over safety mechanism and
inspect to make sure it is operating
properly.

Recently while hunting I had loaded
the chamber and moved the safety to
safe, after locking the bolt with a
live round I moved the safety from
safe to fire and the gun went
off. I don't believe I had my finger
on the trigger during this misfire.
One gun smith I spoke with had told
me that this is a common occurrence
with this particular model. Thank you.

D. H. Conington

103 Marshall Rd.

Glen Mills, Pa. 19342

phone # 610 459-0693