

Set up fill

RECEIVING AND ESTIMATING REPORT				COMMENTS		ORDER	
INITIAL JJM		CUSTOMER ORDER NO.		Product Service		R 94-20326	
DATE RECEIVED 07/01/94	DATE OPENED 07/06/94	DATE CODE PD 6-83	SERIAL NUMBER B6477263	NEW SERIAL NUMBER	MODEL AND GRADE 700 270	ADL	
ACCESSORIES W/STUDS							
FROM: CROY, RICHARD RT 5 BOX 156T ELLIJAY				SHIP TO: CROY, RICHARD RT 5 BOX 156T ELLIJAY			
GA 30540				GA 30540			
CUST NO 999599 C.O.D.L							
ACCOUNT NUMBER		ACCOUNT NUMBER NC		WRITE ☐	PROM. DATE	ESTIMATED	VIA UPS
GUN CONDITION						REPAIR CHARGE	
☐ NEW						EXCISE	
☐ LIGHTLY WORN						TAX	
☐ WORN						INSURANCE	
☐ VERY WORN						UPS	
☐ UNREPAIRABLE						PARCEL POST	
☐ MARRED						TOTAL	
CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT	
CYCLE	A1	B1					
TRIGGER GROUP		B2			E1	F1	
BOLT ASSY.		B3			E2	F2	
BARREL ASSY.		B4			E3	F3	
REC. ASSY.		B5		D2	E4	F4	
WOOD			C1	D3	E5	F5	
METAL			C2				
MAIN FAULT							
Could not duplicate the delay in firing concern. However, removal of the shot from round that this firearm has been properly maintained, a good trigger change is needed. The action, trigger assembly, and firing pin assembly are found with a heavy buildup of a dark sticky substance. Inspection parts are moving sluggish. Rtd 8/1/93 # 36345							
PARTS				COMMENTS			
				Trigger pull 4.4 lbs 3in left O.K. Replace complete trigger assembly and clean action and bolt assembly, at 13 rounds again test, no further delay will. Go ahead			
REPAIRMAN TAL	PROOF	CLEAN	TEST	TARGET	PATTERN		
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE		

OFFICE COPY

RD0925 REV. 1/94