

File Number:	21815	Arms Service number:	103857
Last Name:	CURRAN	First Name:	ROBERT
Street:	159 WILBLU LANE	City:	EXPORT
State:	PA	Zip:	15632
Home Ph:		Home Ph:	724-468-8793
Work Ph:		Product Type:	F A T O
Type Concern:	S	PI	PD P S
Concern:	F I R E D O N B O L T C L O S I N G	Concern Code:	1008
Cause Code:	4015	Cause:	IMPROPER MAINTENANCE
Assigned To:	SUPRY	Classification:	UND
Settlement Detail:	NEW TA N/C	UNJ UNC UND J	
Date Opened Rem:	11/18/2005	Date Opened by PIS:	11/21/2005
Date of Incident:	10/29/2005	Date Closed:	11/21/2005
Date to Analysis:		Date from Analysis:	
Model:	700	Serial:	S6240321
RAMAC:	700	Manufacturer:	REM
Custody:		Date Mfgd:	4/1/1994
Time of Modification:	10:19:28 AM	Obsolete:	
Date of Modification:	11/21/2005	Litigation:	
Comments:	Sear very hard to move, then it sticks down in the housing. Celan action and install new TA at n/c - charge 230/45.		