

Remington.**REMINGTON ARMS COMPANY, Inc.**SPORTING FIREARMS, AMMUNITION, TARGETS AND TRAPS
ILION, NEW YORK 13357

PAGE 1

GROUND SAVER

DATE:

04/06/94


PARTS (315) 895-7493
 REPAIR (315) 895-7791
 FAX (315) 895-7214 (315) 895-3659
 CUSTOMER NUMBER: 93524

SOLD TO

REPAIR ORDER NO.: 94-08252

CURRAN, ROBERT T
 901 MAIN ST
 N HUNTINGDON

PA 15642



WE ACKNOWLEDGE RECEIPT OF THE ITEM(S) DESCRIBED BELOW.

THE NECESSARY CORRECTIONS ARE BEING PERFORMED WITHOUT CHARGE AND PREPAID SHIPMENT WILL BE MADE IN ABOUT 4 WEEKS.

WE KNOW YOU WILL FIND THE REPAIR TO BE COMPLETELY SATISFACTORY AND IF WE CAN HELP YOU IN ANY OTHER WAY, PLEASE LET US KNOW.

700 30-06
 W/STUDS

SS/DDL

SERIAL NUMBER: 56223479

CUSTOMER REQUEST:

GUARD SCREW TOO SHORT IN GUARD ASSEMBLY -
 COVER IN GUARD ASSEMBLY TOO SLOPPY -

MAIN FAULT FOUND:

GUARD SCREWS TOO SHORT, GUARD ASSY. SLOPPY -
 RING IN CHAMBER NEEDS NEW BBL. ASSEMBLY -
 DATE OF MFG: 02-93

1 0105403 FRT GRD SCREW BDL L/A S.S.
 1 0105400 REAR GUARD SCREW (SS)
 1 0097866 TRIG GRD ASSEM BDL L/A S.S.
 9900005 TEST
 9900003 PROOF
 9900006 TARGET
 HOLDING FOR PARTS -

ALL PRICES QUOTED ARE IN EXCHANGE FOR REPLACED PARTSTOTAL REPAIR CHARGE
TAXES

INSURANCE
 PARCEL POST

TOTAL
 CHARGES

NO CHARGE

ARMS SERVICE FILE COPY

PS01460