Date: 11/21/2005

By: FRED SUPRY

FIREARM INSPECTION WORKSHEET

BACKGROUND
Customer name: Robert Curran
R.E. Number: 103857
Reason for inspection: 5EAR 571CKS
<u>FIREARM</u>
Manufacturer: REM Model: 700
Serial Number: 56240321 Date of Manufacture: 20 - 4/94
Overall external condition: 900d
Barrel condition: OK
Receiver condition:
Stock condition: OK
Bolt/firing pin condition: OK
Trigger assembly condition:
Engagement:
Adjustments/alterations:
Other: SEAR hard to move & sticks down
Headspace:
Function evaluation:

Feeding:		<u> </u>
Extraction/ejection:	· · · · · · · · · · · · · · · · · · ·	
Trigger pull: 5 16	·	
Manual safety: OK		
Test firing results (if applicable):		
		· · · · · · · · · · · · · · · · · · ·
Install new TA	N/c-	charge 230145
ADDITIONAL COMMENTS		
·		•
	· · · · · · · · · · · · · · · · · · ·	
enter a company de la comp La company de la		
. ,	·. ·· · · · · · · · · · · · · · · · · ·	
- 		